DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary Report No: WIR-011381
Address: 333 Burma Road Date Inspected: 09-Jan-2010

City: Oakland, CA 94607

Project Name: SAS Superstructure OSM Arrival Time: 645
Prime Contractor: American Bridge/Fluor Enterprises, a JV OSM Departure Time: 1845

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Shanghai, China

CWI Name: CWI Present: Yes Mr. Lu Li Qing No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 Component: Orthotropic Box Girder (OBG)

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA), Vibin Kumar Selvanayaham, was present during the times noted above for observations relative to the work being performed.

Bay 13

This QA inspector observed ZPMC qualified welding personnel identified as 044772 perform Shielded Metal Arc welding (SMAW) welding on Segment 11BE, weld joint identified as SSD18-PP100-253. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214-Tc-U4b-FCM-1.

This QA inspector observed ZPMC qualified welding personnel identified as 200113 perform SMAW welding on Segment 11AE, weld joint identified as SSD19A-PP95-128 & 134. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-P-2214-B-U2-FCM-1.

This QA inspector observed ZPMC qualified welding personnel identified as 055564 perform Flux Cored Arc Welding (FCAW) welding on Segment 11AE, weld joint identified as SSD29-PP96.5-211~234. ZPMC QC is identified as Mr. Guo Xing Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

This QA inspector observed ZPMC qualified welding personnel identified as 044774 & 050242 FCAW Welding on Corner Assembly, weld joint identified as CA094-004. ZPMC QC is identified as Mr. Zhong Guo Hui. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2231-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 048696 Submerged Arc Welding (SAW) Welding on Segment 12BW, weld joint identified as SEG3005A-004. ZPMC QC is identified as Mr. Wang Xu. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2221-B-L2c-S-2.

This QA inspector observed ZPMC qualified welding personnel identified as 045175 FCAW Welding on Deck Panel, weld joint identified as DP269-001-012 & 013. ZPMC QC is identified as Mr. Xu Tao. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2133.

Bay 19

This QA inspector observed ZPMC qualified welding personnel identified as 062783 & 062765 perform FCAW welding on Suspender Bracket, weld joint identified as SB007-036-025, 31, 37, 43, 49, 55, 61 & 67. ZPMC QC is identified as Mr. Zhou Cheng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

This QA inspector observed ZPMC qualified welding personnel identified as 062806 perform FCAW welding on Side Plate, weld joint identified as SP025-013-046. ZPMC QC is identified as Mr. Zhou Cheng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2232-Tc-U4b-F.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar, Vibin	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer